


# ASSEMBLY INSTRUCTION

## ORKNEY CUSHION BOX




NO	HARDWARE LIST		QTY
(A)		BOLTS M6x30	4PCS
(B)		WASHER Ø19xØ6x2	8PCS
(C)		BOLTS (INOX) M6x20	4PCS
(D)		WASHER (INOX) Ø16xØ6x1	4PCS
(E)		HEX NUT M6x6	4PCS
(F)		ALLEN KEY M4x60	1PC
(G)		WRENCH	1PC


### STEP 1




### STEP 2



### STEP 3



### STEP 4



ASSEMBLY COMPLETE

